

# UV Treated N95: Donning & Doffing

## PREPARE BAG & MASK

- 1 Reverse crease sides of bag so it remains open.




- 2 Label the bag:
- Full Name
  - Unit/Dept. return location



- 3 Label N95 Respirator with Sharpie:

- First Initial & Last Name
- Date of first use
- Department location



## INITIAL DONNING

- 1 Don PPE for COVID-19 patient care.



- 2 If wearing goggles, don surgical mask over N95.



## Redonning UV Disinfected N95

- 1 Perform hand hygiene.



- 2 Don gown.



- 3 Don the N95 respirator. Perform a negative/positive seal



- 4 Don face shield or don goggles and procedure mask.



- 5 Perform hand hygiene.



- 6 Don gloves.



# UV Treated N95: Donning & Doffing

## DOFFING

**1** Perform hand hygiene over gloves.



**2** Remove gown & gloves in patient room.



**3** Exit patient room.



**4** Perform hand hygiene and don clean gloves.



**5** Doff surgical mask, if wearing, and store for reuse.




**6** Perform hand hygiene.



**7** Remove goggles or face shield and disinfect.



**8** Store eyewear.



**9** Perform hand hygiene on gloves.



**10** Remove N95 and place into brown "dirty" bag.



**11** Remove gloves and perform hand hygiene.

